

General Environmental Incident Summary

Incident: 5569 **Notice:** 11/8/2017 1630 **Occurred:** 11/8/2017 1630

DEM Incident No:

No Further Action:

Responsible Party: Brady Wind Energy Center

County: Stark

Twp Rng Sec Qtr: 137 96 25

Lat Long + Method: 46.65821 -102.74710 Interpolation from map

Location Description: Brady Wind Energy Center
Site Address: 5206 109th Ave SW, Dickinson, ND 58601
From I-94 Exit 61, 18.5 miles south of Dickinson, ND:
- Follow Hwy-22 S/ 3rd Ave south for 16.5 miles to 52nd St SW, take a left to travel east
- Go east 2 miles on 52nd St SW
- O&M will be on the right of 52nd St SW and 109th Ave SW intersection

Submitted By Info: Chase Dauenhauer
5206 109th Ave SW
Dickinson ND 58601

Received By Info:

Contact Info: Chase Dauenhauer
5206 109th ave SW
Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Gasoline

Volume of Release: 145 gallons

Duration of Release: 10 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Unattended gasoline pump dispenser while fueling a work vehicle

Risk Evaluation:

Flammable fumes

Potential Env. Impacts:

no likelihood to impact water. contained to soil and rocky area.

Action Taken/Planned:

contained, gathered top soil (gravel and Rock) and placed on containment tarp. Covered affected area to prevent snow accumulation in affected area

Wastes Disposal Location:

investigating

Other Agencies Involved:

Updates

Date: 11/8/2017 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas not associated with an exploration and production location. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 11/13/2017 **Status:** Inspection

Author: Martin, Russell

Notes:

11/9/2017 at 11:29, on location. Met with report contact and site personnel. Release occurred at tanks located on southwest corner of lot, and according to the personnel it actually occurred on 11/7/2017 (a day before the listed date). Release appeared to have stayed entirely within the facility fenceline. Lot where release occurred is dirt covered in large (3/4-1 inch) sized gravel. Part of the impacted gravel and dirt beneath has been excavated and piled onto a tarp (with cover). According to report contact, Clean Harbors will be out to finish the cleanup and remove the wastes to their Sawyer landfill. No further follow-up is required at this time, however more follow-up may be required once the disposal records are submitted to the NDDoH.

Updated Volume: None at the time of this update