

General Environmental Incident Summary

Incident: 5652

Notice: 3/9/2018

Occurred: 5/22/2017 1800

DEM Incident No:

No Further Action:

Responsible Party: Dean Foods

County: Burleigh

Twp Rng Sec Qtr: 138 80 3

Lat Long + Method: 46.80494 -100.77280 Interpolation from map

Location Description: Dean Foods
1301 East Main
Bismarck ND

2 locations within this facility. See update for details.

Submitted By Info: Taylor Souder
918 East Divide Ave
Bismarck ND 58501

Received By Info:

Contact Info: Tara Styles
1301 East Main
Bismarck ND 58501

Affected Medium: 09 - other

Near. Occupied Bldg:

Type of Incident: Tank Overflow

Release Contained: No

Reported to NRC: Unknown

Contaminant: Diesel

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

A saddle tank on a semi-tractor was filled and not capped. When the driver drove off, about 5 to 10 gallons of diesel were spilt. Spill occurred by loading docks onto cement.

Risk Evaluation:

no immediate risks

Potential Env. Impacts:

no potential environmental impacts

Action Taken/Planned:

Contact third party consultant.

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 3/9/2018 **Status:** No Further Action Requested

Author: DeVries, Taylor

Notes:

This report was entered into the database by NDDoH Spill Investigation program staff. The NDDoH received a final environmental remediation report for this release, which had not been reported. Upon contacting the responsible party, they did not know of this spill (employee turnover).

There were two locations where diesel fuel was spilled, one in the north loading dock area of Dean Foods (north of railroad tracks) and one at the south loading dock (south of railroad tracks). Both of these releases were small (within 5-10 gallons) and were contained to the asphalt. Floor dry was used to clean up each spot and was properly disposed of at the Bismarck landfill. Report can be found in the report folder. No follow-up needed at this time.

Updated Volume: None at the time of this update