

# General Environmental Incident Summary

**Incident:** 5663                      **Notice:** 3/19/2018    1730    **Occurred:** 3/17/2018    0720

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Keane

**County:** McKenzie

**Twp Rng Sec Qtr:** 152 95 2 SE SE

**Lat Long + Method:** 48.00663    -102.79040    Interpolation from map

**Location Description:** The incident occurred on the shoulder of the lease road at the point marked on the map.

From Keene ND, drive north on HWY 23, follow HWY 23 East, turn north on 104th Ave NW, turn east at 40th street NW, turn North at the "T," drive approximately one mile to the location, marked on the map

**Submitted By Info:** Alex Beach

3015 16TH ST SW STE 20

Minot ND 58701

**Received By Info:**

**Contact Info:** Scott Juma

14079 Co Rd 2

Williston ND 58801

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 1 Miles

**Type of Incident:** Vehicle Accident

**Release Contained:** No

**Reported to NRC:** Unknown

**Contaminant:** 20 g of diesel fuel, and 15,000 lbs of sand

**Volume of Release:** 20 gallons

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely**

**Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

A tractor operator lost control of tractor and trailer, after crossing a cattle guard. As a result, the tractor trailer rolled 3/4 times, releasing approximately 20 gallons of diesel fuel and 15,000 pounds of sand.

**Risk Evaluation:**

The tractor operator did not sustain any injuries when the tractor trailer rolled 3/4 times.

**Potential Env. Impacts:**

A response team constructed a dirt berm 20' north of the spill area to contain the diesel fuel. The impacts were contained to the soil, at the location of the release.

**Action Taken/Planned:**

A response team constructed a dirt berm 20' north of the spill area to contain the diesel fuel. A wrecker operator positioned the tractor and trailer in an upright position on the road. The response team created an emergency one call, and collected soil samples for lab analysis. The Hess Land Department contacted the property owner. An environmental contractor will recover the impacted

materials.

**Wastes Disposal Location:**

All recovered materials will be disposed at an approved waste disposal facility.

**Other Agencies Involved:**

**Updates**

---

**Date:** 3/19/2018      **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Notes:**

Vehicle accident on lease road. Follow-up is required.

**Updated Volume:** None at the time of this update

---

**Date:** 3/23/2018      **Status:** Inspection

**Author:** Schiermeister, Robin

**Notes:**

Arrived on site at 12:56 on 3-20-2018. It was cloudy with temperatures in the 30's. Release went east off the road and has been scraped up. The berm mentioned in the report is still in place. Walked up and down the area and could not see any signs of contamination. Took samples of the creek, east of the site. No further onsite inspection is needed, just the sample analyses to confirm if clean up was successful.

**Updated Volume:** None at the time of this update

---

**Date:** 5/31/2018      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Received an email from the company contact with a Remediation Summary and Closure Request attached. Review of the report shows that confirmation samples collected from the area impacted by the diesel release were No Detect. No further action is needed at this time. Report added to the incident folder.

**Updated Volume:** None at the time of this update

---

**Date:** 5/31/2018      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Brian O'Gorman sent a No Further Action letter dated May 31, 2018.

**Updated Volume:** None at the time of this update