

General Environmental Incident Summary

Incident: 5716

Notice: 5/15/2018

Occurred: 5/15/2018 0500

DEM Incident No:

No Further Action:

Responsible Party: Cudd Energy Services

County: McKenzie

Twp Rng Sec Qtr: 152 101 6

Lat Long + Method: 48.01358 -103.65900 Interpolation from map

Location Description: Ditch on the side of Hwy 85 just south of 45th M St NW and due south of Williston, ND

Submitted By Info: Jeffrey Cart
1005 RPC Energy Dr.
Broussard LA

Received By Info:

Contact Info:

13902 Sunset Blvd
Williston, ND ND 58801

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: ruptured diesel tank

Release Contained: No

Reported to NRC: Unknown

Contaminant: diesel fuel

Volume of Release: 100 gallons

Duration of Release: 10 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

semi hit debris in the roadway which was thrown by the tire into a diesel tank leaving 1-2 inch puncture in the tank

Risk Evaluation:

NA

Potential Env. Impacts:

Impacted soil has been excavated.

Action Taken/Planned:

Highway patrol was notified as was Treadstone Environmental for remediation. Affected area along the roadway has been excavated and confirmation samples were taken. Area will be back filled and sodded.

Wastes Disposal Location:

Other Agencies Involved:

State Highway Patrol, Local Fire Department

Updates

Date: 5/15/2018 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 100 gallons of diesel fuel was released onto a roadway and ditch. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 5/21/2018 **Status:** Inspection

Author: Schiermeister, Robin

Notes:

Arrived on site at 16:35 on 5-15-2018. It was sunny with temperatures in the 70's. Called party representative who said the emergency manager of McKenzie county said they don't have to send in their confirmation samples and that everything looked good. Walked around the area and could not find the specific spot. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 5/21/2018 **Status:** Inspection

Author: Schiermeister, Robin

Notes:

Talked to party representative on 5-16-2018 who said that the release actually happened south of 45th St NW, not 41st St NW. Note that this location information has been changed in the master record of the database.

I checked out the updated area at 12:40 on 5-16-2018. It was sunny with temperatures in the 70's. The area has been excavated and new topsoil laid down. There was no staining or odor present. There was also sparse vegetation. The emergency manager has visited the site and gave the responsible party permission to close it. No further follow-up is needed.

Updated Volume: None at the time of this update