

General Environmental Incident Summary

Incident: 5774 **Notice:** 7/3/2018 1630 **Occurred:** 7/3/2018 1515

DEM Incident No:

No Further Action:

Responsible Party: Central Power

County: Burleigh

Twp Rng Sec Qtr: 139 80 36

Lat Long + Method: 46.81372 -100.72730 Interpolation from map

Location Description: 701 North Bismarck Expy
Bismarck, ND 58503

Submitted By Info: Mark Sherman
Central Power
525 20th Ave SW
Minot ND 58701

Received By Info:

Contact Info: Mark Sherman
525 20th Ave SW
Minot ND 58701

Affected Medium: 03 - soil

Near. Occupied Bldg: 2200 Feet

Type of Incident: Tank Leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Mineral Oil

Volume of Release: 100 gallons

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Electrical regulator fault burned through tank creating mineral oil spill in electrical substation.

Risk Evaluation:

no immediate risks

Potential Env. Impacts:

remaining "free" oil has been absorbed with absorbents and the remaining oil has been contained in the substation's soil and rock within an approximate footprint of 8' x 15'.

Action Taken/Planned:

Dried spill as much as possible with absorbents. Contacted Strata Corporation to perform cleanup. Strata will be on site at the substation on 7/5/18 to remove all contaminated soil and rock. We will then backfill the area with clean material.

Wastes Disposal Location:

Strata Corporation will properly dispose of the contaminated material.

Other Agencies Involved:

Updates

Date: 7/3/2018 **Status:** Reviewed - Assigned to NDDEQ Division

Author: Striebel, Ivana

Notes:

This incident has been assigned to the Division of Waste Management, Hazardous Waste program because of the contaminant.

Updated Volume: None at the time of this update

Date: 7/5/2018 **Status:** Correspondence

Author: Striebel, Ivana

Notes:

7/5/2018 - Spoke to responsible party. They emailed photos of the spill and will send in information about spill cleanup and proof that the mineral oil is not PCB. Further action needed.

Updated Volume: None at the time of this update

Date: 7/6/2018 **Status:** Correspondence

Author: Striebel, Ivana

Notes:

7/6/2018 - Received nameplate information, this spill did not contain PCBs. This spill has been cleaned and spill debris has been sent to a proper disposal facility. No further action needed.

Updated Volume: None at the time of this update