

General Environmental Incident Summary

Incident: 5778 **Notice:** 7/8/2018 1215 **Occurred:** 7/8/2018 0800

DEM Incident No:

No Further Action: ☒

Responsible Party: Plains Marketing

County: McKenzie

Twp Rng Sec Qtr: 147 104 24

Lat Long + Method: 47.54765 -104.00100 Navigation quality GPS

Location Description: Six miles east of the Montana border on Hwy 68

Submitted By Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 1.5 Miles

Type of Incident: truck hose leak

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude oil

Volume of Release: 2 barrels

Duration of Release: 5 minutes

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Driver left valve open while loading

Risk Evaluation:

None

Potential Env. Impacts:

Soil

Action Taken/Planned:

Contained spill in loading area and excavated into a container.

Wastes Disposal Location:

Chimney Butte Landfill

Other Agencies Involved:

US Forest Service

Updates

Date: 7/8/2018 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release, due to a truck hose leak, impacted a loading area, according to the report. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 7/9/2018 **Status:** Correspondence

Author: Harries, Alison

Notes:

According to the responsible party contact, the report had been filed with an incorrect lat/long coordinate, township, range, section and distance to nearest occupied residence. The contact subsequently emailed the correct location and distance data to the NDDoH. It has been corrected in the database.

Updated Volume: None at the time of this update

Date: 7/10/2018 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Notes:

Release due to improper loading operation (driver did not connect loading hose properly), release remained on location (101 Federal 21X-24 wellpad), according to report (see Oil Field Environmental Incident Report #20180709121828). NDIC retains oversight. This duplicate report will be closed.

Updated Volume: None at the time of this update