General Environmental Incident Summary

Incident: 5789	<i>Notice:</i> 7/17/2018 1531 <i>Occurred:</i> 7/17/2018 1200
DEM Incident No:	No Further Action: 🔽
Responsible Party:	Andeavor Dickinson Refinery
County:	Stark
Twp Rng Sec Qtr:	139 97 15
Lat Long + Method:	46.85575 -102.89970 Interpolation from map
Location Description:	3815 116th Ave SW Dickinson, ND 58601
Submitted By Info:	Tonya Woolery
	Environmental Specialist
	3815 116th Ave SW
	Dickinson ND 58601
Received By Info:	
Contact Info:	Tonya Woolery
	3815 116th Ave SW
	Dickinson ND 58601
Affected Medium:	03 - soil
Near. Occupied Bldg:	
Type of Incident:	Truck overflow
Release Contained:	No
Reported to NRC:	No
Contaminant:	Diesel Fuel - non-dyed
Volume of Release:	25 gallons
Duration of Release:	
Agriculture Related:	No
EPA Extremely	
Hazardous Substance:	No
Number of Fatalities:	0
Number of Injuries:	0
Cause of Incident:	

After completing the loading process, a common carrier driver pulled out of Diesel lane 3. Trailer had a 4" service hose uncapped, that was not used during the loading process. When he drove over the incline coming out of the lane, the diesel in the hose spilled out and ran on to the cement and pavement. The release amount was calculated to be 25 gallons onto asphalt.

Risk Evaluation:

No immediate health hazards or explosive atmospheres.

Potential Env. Impacts:

Spill area was to the asphalt in the terminal. Surface water in the terminal flows to a refinery storm water drain that drains to storm water pond. Storm water drain was covered and oil boom was deployed as preventive measure around drain. Storm water pond is monitored for sheen prior to release to the outfall.

Action Taken/Planned:

Driver was stopped and cap was replaced. Spill was cleaned up, and storm water drains were covered.

Wastes Disposal Location:

Recovered wastes will be disposed of at Clean Harbors, Sawyer landfill. *Other Agencies Involved:*

Updates

Date: 7/18/2018 Status: Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Follow-up required due to insufficient details about clean-up.

Updated Volume: None at the time of this update

Date: 7/18/2018 *Status:* Correspondence

Author: Crowdus, Kory

Notes:

Spoke with contact and requested some additional information regarding cleanup and to provide some photos. No on-site inspection needed at this time. Further follow-up is required.

Updated Volume: None at the time of this update

Date: 7/19/2018 Status: Correspondence

Author: Crowdus, Kory

Notes:

Received some photos where incident occurred. Kitty litter was used to absorb fuel and was disposed of. No further follow-up required.

Updated Volume: None at the time of this update

Date: 7/30/2018 Status: Correspondence

Author: Sandvick, Duane

Notes:

Duane Sandvick sent a No Further Action letter dated July 30, 2018.

Updated Volume: None at the time of this update