# General Environmental Incident Summary

*Incident:* 5823 *Notice:* 8/23/2018 1346 *Occurred:* 5/11/2018 1200

DEM Incident No: No Further Action: 

✓

Responsible Party: Randy Brym
County: Mercer

**Twp Rng Sec Qtr:** 146 87 9 NW

Lat Long + Method: 47.48679 -101.78000 Interpolation from map

Location Description: 5801 LAKESHORE EST 38, BEULAH

LOT 38 BLK 1 LAKE SHORE SUB

**Submitted By Info:** Bree Fode

State Farm 201 N 19th St

Bismarck ND 58501

Received By Info:

**Contact Info:** Bree Fode

5801 Lakeshore Est #11B

Beulah ND 58523

Affected Medium: 03 - soil
Near. Occupied Bldg: 20 Feet

Type of Incident: Oil and chemicals spill from Lot 11B and saturated soil. Creeping up nearby

Release Contained: No Reported to NRC: Unknown

Contaminant: Unknown - Oil and other chemicals used in semi-trucks as the shop is a

semi repair shop.

Volume of Release:

Duration of Release:

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: Unknown

Number of Fatalities: Number of Injuries: Cause of Incident:

This individual was dumping this liquid into the ground. In addition he had a fire on his property that released unknown amounts of used motor oil and other harmful chemicals affecting not only his but neighbor's property located at 5801 Lakeshore Est #38

#### Risk Evaluation:

unknown

#### Potential Env. Impacts:

Soil is definitely affected. Oil and chemicals starting to saturate fence and yard at this location.

## Action Taken/Planned:

nothing has been done at this point in time.

Wastes Disposal Location:

Other Agencies Involved:

### **Updates**

Date: 8/23/2018 Status: Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Dumping of oil and chemicals to the ground. Follow-up is required.

Updated Volume: None at the time of this update

Date: 9/5/2018 Status: Inspection

Author: Stockdill, Scott

Notes:

Arrived on location 10:57 9/5/2018.

Minimal amount of impacts from hydrocarbons. One small area near fence and some where the waste oil heater was. Responsible party is going to be cleaning up impacted soil this weekend. Whole site where the shop burned down will be removed and regraded in the coming months.

No follow-up is necessary.

Updated Volume: None at the time of this update