

General Environmental Incident Summary

Incident: 5851

Notice: 9/14/2018

Occurred: 9/11/2018

DEM Incident No:

No Further Action:

Responsible Party: Precision Underground Inc

County: McKenzie

Twp Rng Sec Qtr: 152 98 15

Lat Long + Method: 47.98716 -103.20130 Interpolation from map

Location Description: Half mile directly west of Gunderson home place

Submitted By Info: Cameron Fish
2607 Franklin Ave
Baldwin ND

Received By Info:

Contact Info:

PO Box 2618

Bismarck ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Inadertant Flow

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Bentonite and water

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Too much downhole pressure caused cuttings to surface

Risk Evaluation:

no immediate risk

Potential Env. Impacts:

no environmental impact

Action Taken/Planned:

stopped work and put up silt fence

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 9/14/2018 **Status:** Reviewed - No Action Required

Author: Stockdill, Scott

Notes:

According to the responsible party, this release involved a small amount of inert material that was immediately cleaned up. No follow-up is necessary.

Updated Volume: None at the time of this update