

General Environmental Incident Summary

Incident: 5910

Notice: 11/21/2018 1245

Occurred: 11/20/2018 1315

DEM Incident No:

No Further Action: ☒

Responsible Party: Plains Marketing

County: Mountrail

Twp Rng Sec Qtr: 156 91 8

Lat Long + Method: 48.30240 -102.37470 Navigation quality GPS

Location Description: 1/4 mile south on Hwy 8 from the intersection with Hwy 2 in Stanley, ND. East side of Hwy on 1st parallel gravel frontage road. Spill location is located around pump behind three 1,000 bbl tanks inside dike.

Submitted By Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 0.25 Miles

Type of Incident: Pump Leak

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude oil

Volume of Release: 1.25 barrels

Duration of Release: 4 hours

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Leak from pump seal

Risk Evaluation:

None

Potential Env. Impacts:

Soil

Action Taken/Planned:

Stopped pump and repaired seal. Contaminated soil will be excavated into drums pending disposal.

Wastes Disposal Location:

Prairie disposal

Other Agencies Involved:

Updates

Date: 11/23/2018 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release was not contained. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 12/11/2018 **Status:** Inspection

Author: DeVries, Taylor

Notes:

Inspection Date: 12/11/2018

Arrived on location at 0930. The release was contained within the berm and contaminated gravel has been removed. No further follow-up needed at this time. No photos taken.

Updated Volume: None at the time of this update