

General Environmental Incident Summary

Incident: 5942

Notice: 12/20/2018

Occurred: 12/19/2018 1430

DEM Incident No:

No Further Action:

Responsible Party: precision Underground

County: Williams

Twp Rng Sec Qtr: 153 98 4 SE

Lat Long + Method: 48.09995 -103.28190 Navigation quality GPS

Location Description: Thomas 44-4

Submitted By Info: Donald Billingsley
2712 E Rosser ave
Bismark ND

Received By Info:

Contact Info:

1800 E Broadway Ave suite 400
Bismark ND

Affected Medium: 03 - soil

Near. Occupied Bldg: 1 Miles

Type of Incident: Bore frac out

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Bentinite

Volume of Release: 20 barrels

Duration of Release: 30 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Bore mud went to the path of least resistance

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

Hydrovac

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 12/20/2018 **Status:** Reviewed - No Action Required

Author: Martin, Russell

Notes:

According to the incident summary, this spill occurred during pipeline construction and occurred within the pipeline right-of-way. Discussion with personnel onsite did confirm ~20 bbl volume, (personnel estimate it to be less than 1,000 gal). Multiple hydrovacs removing the mud, planning on getting it all removed today. No water impacts. Similar incident was inspected to confirm proper cleanup was performed (see incident #5818). Based on actions taken by the responsible party and material involved, no further follow-up is necessary at this time.

Updated Volume: None at the time of this update