

General Environmental Incident Summary

Incident: 5949

Notice: 1/7/2019

Occurred: 1/7/2019

DEM Incident No:

No Further Action:

Responsible Party: MRL Trucking

County: Stark

Twp Rng Sec Qtr: 140 96 21

Lat Long + Method: 46.93296 -102.78980 Interpolation from map

Location Description: North on Highway 22 AB Dick & send near the John Deere dealership

Submitted By Info: Rick Lucas

Same

Same ND

Received By Info:

Contact Info:

4949 162nd Avenue Northeast

Baldwin North Dakota ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Vehicle Accident

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Diesel fuel

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Driver drove off road

Risk Evaluation:

None

Potential Env. Impacts:

I don't know

Action Taken/Planned:

Soil excavated refilled and planted

Wastes Disposal Location:

Other Agencies Involved:

Bi

Updates

Date: 1/7/2019 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 1/25/2019 **Status:** Inspection

Author: Washek, Sandi

Notes:

Arrived onsite at 11:49am weather was partially sunny with wind out of the west at 15 miles/hr., temperature of 15 degree F.

The accident is located in the SE corner of the intersection. You can see where the light pole has been replaced. At the time of the inspection the ground was covered in fresh snow. Could not see any staining of pavement in the area. Will need to return in spring for additional follow-up.

Updated Volume: None at the time of this update

Date: 3/29/2019 **Status:** Correspondence

Author: O'Gorman, Brian

Notes:

Received an email from Kirk Johnson from the Waste Management Division with a disposal receipt from Sawyer Disposal on 3/21/2019. The receipt showed 12.68 tons of diesel contaminated soil disposed at the landfill. Receipt added to the incident folder. More follow-up needed.

Updated Volume: None at the time of this update

Date: 3/20/2020 **Status:** Inspection - No Action Required

Author: Schiermeister, Robin

Notes:

Arrived on site at 11:45 CT on 3-19-2020. The ground was snow covered and temperatures were in the teens. There was no good place to pull over; however, during a drive-by it appeared that vegetation did grow back. It was brown and dead due to the temperatures but it did grow. No further follow-up is necessary due to the lack of evidence of historical contamination. No photos were taken.

Updated Volume: None at the time of this update