General Environmental Incident Summary

Incident: 5952 *Notice:* 1/9/2019 1315 *Occurred:* 1/8/2019 1311

DEM Incident No: No Further Action: ✓

Responsible Party: Plains Marketing

County: McKenzie
Twp Rng Sec Qtr: 153 94 35

Lat Long + Method: 48.02444 -102.72600 Navigation quality GPS

Location Description: 10 miles northwest of New town, ND -- west of the lake bridge.

Submitted By Info: Daniel Holli

P.O. Box 708

Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli

P.O. Box 708

Belfield ND 58622

Affected Medium: 03 - soil
Near. Occupied Bldg: 1 Miles

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: Unknown

Crude oil condensate

Volume of Release: 4 barrels

Duration of Release: 2 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: No Number of Fatalities: 0 Number of Injuries: 0

Cause of Incident:

Contract driver from Hoffman trucking overfilled his truck while loading.

Risk Evaluation:

None

Potential Env. Impacts:

Soil

Action Taken/Planned:

All impacts stayed on compressor station property.

Impacted soils will be excavated into bins for storage pending analysis and disposal.

Wastes Disposal Location:

Prairie Disposal

Other Agencies Involved:

Updates

Date: 1/9/2019 Status: Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this release occurred at a location not associated with

exploration and production. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 1/16/2019 Status: Inspection

Author: Stockdill, Scott

Notes:

Arrived on location 1/16/2019 10:30.

Release from tanks of condensate flowed into pooling area. Site is being excavated with most of the impacted materials being removed. There is a culvert the spill may have possibly travelled down. Consultant onsite is going to take a sample to confirm the spill didn't travel down it.

No onsite follow-up is necessary.

Updated Volume: None at the time of this update

Date: 3/14/2019 Status: Correspondence - More Follow-up Required

Author: Stockdill, Scott

Notes:

Email from consultant for the responsible party.

"...Attached is the final report for the Elm Tree Compressor Station Response – EIR# 5952. Please review at your earliest convenience and do not hesitate to reach out to Kurtis or myself if you have any questions, comments or concerns. I will be available by email or cell all weekend. ..."

Full email and attachments in report folder.

Updated Volume: None at the time of this update