

Updates

Date: 1/14/2019 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release, due to a struck gas line, impacted soils at the site, according to the report. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 1/15/2019 **Status:** Inspection

Author: Stockdill, Scott

Notes:

Arrived on location 2:08 1/15/2019.

There is a small area outside fence that has been recently excavated and backfilled. No sign of visual contaminants at site.

More follow-up in spring to ensure regrowth of vegetation.

Updated Volume: None at the time of this update

Date: 6/10/2019 **Status:** Inspection

Author: Striebel, Ivana

Notes:

5/30/2019 - Onsite at 2:56 pm, sunny and hazy, 80° F, light breeze. This 12 bbl release was located on the east side of this salt water pad. Responsible party was removing their lines leading up to what was an oil well, but had been converted to a saltwater disposal well. They were sweeping their lines clean for abandonment not knowing that the line had been compromised. Line was capped on both ends and abandoned in place. Hole has been back filled, site has not been re-vegetated and should be re-checked at a later date to insure that site has been properly reclaimed. Further action needed.

Updated Volume: None at the time of this update

Date: 8/23/2019 **Status:** Correspondence

Author: Striebel, Ivana

Notes:

7/19/2019 - Received correspondence from State Lands Department, state of North Dakota is the landowner. Lands Dept representative visited this site and has no concerns regarding this release and is satisfied with revegetation. No further action needed.

Updated Volume: None at the time of this update

Date: 8/23/2019 **Status:** Correspondence

Author: Striebel, Ivana

Notes:

Ivana Striebel sent a No Further Action letter dated August 23, 2019.

Updated Volume: None at the time of this update