

General Environmental Incident Summary

Incident: 5956

Notice: 1/13/2019

Occurred: 1/11/2019

DEM Incident No:

No Further Action:

Responsible Party: Precision Underground Inc

County: McKenzie

Twp Rng Sec Qtr: 153 97 13

Lat Long + Method: 48.07968 -103.10380 Interpolation from map

Location Description: 1 Mile south of Tobacco Gardens resort on the Southeast side of 1806 on the curve

Submitted By Info: Cameron Fish
2607 Franklin Ave
Baldwin ND

Received By Info:

Contact Info:
PO Box 2618
Bismarck ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Inadertant Flow

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Water and Bentonite

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

To Much down hole pressure caused ground to fracture and release returns

Risk Evaluation:

no immediate risk

Potential Env. Impacts:

no environmental impacts

Action Taken/Planned:

stopped worked and contained mess and began clean up

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 1/14/2019 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release, due to excessive pressure, impacted soil, according to the report. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 4/9/2019 **Status:** Reviewed - No Action Required

Author: Martin, Russell

Notes:

According to the incident summary, this spill occurred during pipeline construction. Due to the actions taken by the responsible party, no onsite follow-up required at this time. Similar incident was inspected to confirm proper cleanup was performed (see incident #5818). Left message with report contact to determine volume lost.

Updated Volume: None at the time of this update