General Environmental Incident Summary

Incident: 5959 Notice: 1/17/2019 Occurred: 1/14/2019

DEM Incident No: No Further Action: ✓

Responsible Party: BNSF Railway

County: Morton

Twp Rng Sec Qtr: 139 81 26

Lat Long + Method: 46.82822 -100.87180 Interpolation from map

Location Description: BNSF Railway

300 1st SW Mandan, ND

Submitted By Info: Matt Richardson

604 7th Street North

Wilton ND

Received By Info:

Contact Info: Greg Jeffries

300 1st St SW Mandan ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Locomotive Gear Box Failure

Release Contained:YesReported to NRC:UnknownContaminant:Gear Oil

Volume of Release: 12 gallons

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: Number of Injuries: Cause of Incident:

Locomotive Traction Motor Malfunction.

Risk Evaluation:

No immediate risk to human health.

Potential Env. Impacts:

No environmental impacts are expected. Impacted soils were excavated. Recovered soils and absorbents were containerized and are awaiting disposal.

Action Taken/Planned:

Free product was mitigated via absorbents. Impacted soil was excavated.

Wastes Disposal Location:

Clean Harbors Landfill in Sawyer, ND.

Other Agencies Involved:

Updates

Date: 1/17/2019 Status: Awaiting Documentation

Author: Martin, Russell

Notes:

Release, due to locomotive gear box failure, on BNSF property. Further review pending report from

BNSF consultant.

Updated Volume: None at the time of this update

Date: 9/9/2019 Status: Correspondence

Author: Martin, Russell

Notes:

Received cleanup report from contractor on 8/29/2019. No further follow-up required.

Updated Volume: None at the time of this update

Date: 12/2/2019 Status: Correspondence - No Action Required

Author: Martin, Russell

Notes:

Russell Martin sent a No Further Action letter dated November 29, 2019.

Updated Volume: None at the time of this update