

# General Environmental Incident Summary

**Incident:** 8070

**Notice:** 5/13/2019 2315

**Occurred:** 5/13/2019 1445

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Precision Underground

**County:** Williams

**Twp Rng Sec Qtr:** 154 100 13

**Lat Long + Method:** 48.15633 -103.49180 Interpolation from map

**Location Description:** From 1804 head north 100 yards to first left turn heading west on lease road to well pad. Travel 50 yards on lease road and frack out would be found.

**Submitted By Info:** Aaron Amstadt  
Foreman Precision Underground  
1800 E Broadway Ave, Suite 400  
Bismarck ND 58501

**Received By Info:**

**Contact Info:** Tyler Blauert  
1800 E Broadway Ave, Suite 400  
Bismarck ND 58501

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 0.25 Miles

**Type of Incident:** inadvertent drilling fluid release

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** Water. No additives.

**Volume of Release:** 50 gallons

**Duration of Release:** 10 minutes

**Agriculture Related:** No

**EPA Extremely  
Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Flow from bore hole packed off and pressured up causing mud to come up through the lease road instead of the entry or exit hole of the bore.

**Risk Evaluation:**

None

**Potential Env. Impacts:**

No environmental impacts.

**Action Taken/Planned:**

Boring was ceased, water was contained, mud was scooped up and put back in catch hole. Reamer was pushed out to open hole and hydrovac will be onsite for the duration of operations.

**Wastes Disposal Location:**

With the rest of the bore mud.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 5/13/2019      **Status:** Reviewed - No Action Required

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, only a small amount of freshwater was released. No follow-up is necessary.

**Updated Volume:** None at the time of this update