

Updates

Date: 5/17/2019 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 1/24/2020 **Status:** Inspection - No Action Required

Author: Stockdill, Scott

Notes:

Arrived on location 2:30 1/24/2019.

Small amount of lime still present in the railroad ballast. Release is unlikely to impact areas outside of the railroad ballast.

No follow-up is necessary.

Updated Volume: None at the time of this update