## General Environmental Incident Summary

Incident: 8137 Notice: 6/29/2019 1722 Occurred: 6/29/2019 1100

DEM Incident No: No Further Action: 

✓

Responsible Party: Stallion Rockies

County: Williams

Twp Rng Sec Qtr: 154 98 18

Lat Long + Method: 48.15460 -103.32890 Interpolation from map

Location Description: East of Williston on 1804. Between 123 Ave NW and 122 Ave NW south

side of road

Submitted By Info: Jerrid Kierig

14070 49th St NW Williston ND 58801

Received By Info:

Contact Info: Jerrid Kierig

14070 49th St NW Williston ND 58801

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Vehicle Accident

Release Contained: Yes
Reported to NRC: Unknown

Contaminant: Died Off Road Diesel Fuel

Volume of Release: 280 gallons

**Duration of Release:** 

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: No

Number of Fatalities: Number of Injuries: Cause of Incident:

Vehicle Accident. Generator being pulled rolled over spilling the contents of the fuel tank.

Risk Evaluation:

None

Potential Env. Impacts:

Soils

Action Taken/Planned:

Road side containment kit utilized. Badger Daylights used hydrovac to remove contaminated soil.

Wastes Disposal Location:

Pending

Other Agencies Involved:

State Highway Patrol, Local Law Enforcement

Friday, June 3, 2022 Page 1 of 3

## **Updates**

Date: 7/1/2019 Status: Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, there was a release of 280 gallons of diesel fuel due to a truck

accident. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 7/2/2019 Status: Inspection

Author: O'Gorman, Brian

Notes:

On location at 6:44. Observed the site and took photos. It appeared that the area where the diesel had impacted soil and vegetation had been hydro-vac'd due to soil and vegetation being removed to a depth of approximately 2 feet. The remaining soils and vegetation did not show any petroleum staining. Replacement soil will be needed for the area excavated. More follow-up needed. Photos added to the incident folder.

**Updated Volume:** None at the time of this update

Date: 8/8/2019 Status: Inspection

Author: Torgerson, Brad

Notes:

On 8/8/2019 at 4:38 PM - Sunny and 78 Degrees F - I visited the Stallion Rockies accident site immediately south of HWY 1804 in Williams County. An excavated area, lacking vegetation, and measuring approximately 10 feet east to west and 2 feet north to south and 2 feet deep was noted within the Hwy 1804 southern ditch. No petroleum odors or stains were noted.

Updated Volume: None at the time of this update

Date: 4/14/2020 Status: Inspection - More Follow-up Required

Author: Lund, Dylan

Notes:

Arrived on location at 1505 4-14-2020

Ditch south of 1804 at accident site is mechanically disturbed. Area is not remediated due heavy machinery movement but could potentially be from nearby pipeline work. Follow-up required for more details of remediation efforts.

Photos were taken and are in report folder.

**Updated Volume:** None at the time of this update

Friday, June 3, 2022 Page 2 of 3

Date: 10/13/2021 Status: Inspection - No Action Required

Author: Lund, Dylan

Notes:

Arrived on location at 1:35 on 10-13-2021.

Inspected area where accident happened. No sign of any remaining impacts or environmental concerns. After reviewing previous photos with photos taken at the time of inspection, vegetation has recovered and is healthy. No follow-up is required. Photos were taken and can be found in the incident folder.

Updated Volume: None at the time of this update

Friday, June 3, 2022 Page 3 of 3