General Environmental Incident Summary

			●	
Incident: 8139	Notice: 7/1/2019	Occurred:	6/29/2019	
DEM Incident No:			No Further Act	ion: 🗸
Responsible Party:	BNSF Railway			
County:	Ward			
Twp Rng Sec Qtr:	155 82 24			
Lat Long + Method:	48.23828 -101.16250	Interpolation from map)	
Location Description:	BNSF Railway 6400 4th Ave NE Minot			
Submitted By Info:	Matt Richardson			
	604 7th Street North			
	Wilton ND			
Received By Info:	MN - Minnesota Jeffries			
Contact Info:	Greg Jeffries			
	80-44th Ave NE			
	Minneapolis MN			
Affected Medium:	03 - soil			
Near. Occupied Bldg:				
Type of Incident:	Locomotive Fuel Tank Leak			
Release Contained:	Yes			
Reported to NRC:	Unknown			
Contaminant:	Diesel Fuel			
Volume of Release:	5 gallons			
Duration of Release:	5 minutes			
Agriculture Related:	No			
EPA Extremely Hazardous Substance:	Unknown			
Number of Fatalities:				
Number of Injuries:				
Cause of Incident:				
Lessenstive fuel tenk vener relief line molfunction				

Locomotive fuel tank vapor relief line malfunction.

Risk Evaluation:

No immediate risk to human health.

Potential Env. Impacts:

Potential environmetnal impacts should be minimal. Impacted materials were excavated and containerized for disposal at a licensed facility. Booms were placed near release area as a precaution.

Action Taken/Planned:

Spill was noticed by train crew. Containment was immediately placed under locomotive. Impacted ballast was excavated and containerized. Boom was placed next to release area and in stormwater ditch as a precautionary measure. Continued monitoring for the site will be conducted.

Wastes Disposal Location:

Clean Harbors Landfill in Sawyer, ND.

Other Agencies Involved:

Updates

Date: 7/1/2019 Status: Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, 5 gallons of fuel was lost on the train ballast. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 9/12/2019 *Status:* Correspondence

Author: Suess, Bill

Notes:

The RP has been contacted and asked to provide a status update on this site. The DEQ is waiting on the response.

Updated Volume: None at the time of this update

Date: 4/17/2020 Status: Correspondence - No Action Required

Author: Martin, Russell

Notes:

Received cleanup report from contractor on 4/3/2020. No further follow-up required.

Updated Volume: None at the time of this update