

General Environmental Incident Summary

Incident: 8149

Notice: 7/10/2019

Occurred: 7/10/2019

DEM Incident No:

No Further Action:

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY

County: McKenzie

Twp Rng Sec Qtr: 149 96 18

Lat Long + Method: 47.73006 -103.02510 Address matching

Location Description: Hwy 23 east of Watford City, to Johnson's Corner. Turn right (south) on CR 53 go 3.9 miles to CR 45. Turn right (west) on CR 45 and go 1.2 miles turn Left (south) and travel 2.1 miles to Lease Rd. Turn right on Lease Rd and travel 2 miles to location.

Submitted By Info: Kelsy Waggaman
11090 30th Street SW
Dickinson ND

Received By Info:

Contact Info: 925 N Eldridge
Houston TX

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Valve leak

Release Contained: No

Reported to NRC: No

Contaminant: Diesel fuel

Volume of Release: 29 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Fuel separator pod/ fuel valve on generator package was found open and leaking diesel fuel at 9am MT on 7/10/19. Generator was not running. Diesel was released directly to facility topsoil. All spilled material stayed on location. Volume of diesel released was calculated from volume of fuel delivery on 7/9 minus estimated fuel usage. Generator package is owned and operated by Nabors Drilling.

Risk Evaluation:

None

Potential Env. Impacts:

Diesel fuel on facility topsoil

Action Taken/Planned:

Leak stopped when fuel valve was closed.

Wastes Disposal Location:

TBD, will be coordinated with BLM and Forest Service.

Other Agencies Involved:

Updates

Date: 7/10/2019 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release of diesel was contained on the well pad TAILGUNNER. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 7/11/2019 **Status:** Reviewed - Follow-up Required

Author: Washek, Sandi

Notes:

Company rep called and updated amount of volume spill to only 7.8 barrels.

Updated Volume: 7.8 barrels

Date: 8/6/2019 **Status:** Inspection

Author: Crowdus, Kory

Notes:

At location 8/6/2019, at 1:47pm. Drilling rig is on site and location is gated off. Will need to follow-up at a later date.

No photos taken.

Updated Volume: None at the time of this update

Date: 8/3/2020 **Status:** Inspection - No Action Required

Author: Crowdus, Kory

Notes:

At location 8/3/2020, at 4:13pm. A lot of activity on site because site has a workover rig at the location. I drove through the site and no visible staining or impacts were seen. No further follow-up is required.

No photos taken.

Updated Volume: None at the time of this update