

General Environmental Incident Summary

Incident: 8151

Notice: 7/11/2019

Occurred: 7/9/2019 1:00

DEM Incident No:

No Further Action:

Responsible Party: Aggregate Industries

County: Barnes

Twp Rng Sec Qtr: 140 60 25

Lat Long + Method: 46.91878 -98.19583 Interpolation from map

Location Description: The spill occurred at the paving job site located on I-94 at the intersection of Barnes County Highway 1 on the south side of I-94.

Submitted By Info: Patty Bestler
2815 Dodd Road, Suite 101
Eagan MN

Received By Info:

Contact Info: 2815 Dodd Road, Suite 101
Eagan ND 55121

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Hydraulic Line Burst

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Hydraulic Oil

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

The hydraulic line on a haul truck burst on the job site. The haul truck belongs to North Country Contracting, who is one of Aggregate Industries' Independent Haulers. Approximately 25 gallons of hydraulic oil spilled onto the ground.

Risk Evaluation:

None

Potential Env. Impacts:

No waters of the state were impacted.

Action Taken/Planned:

The driver (Adam) from North Country Contracting was told "not to worry" about the spill by one of the on-site workers from Gowan Construction, as Gowan would take care of cleaning up the contaminated material. Although this was an Independent Hauler for Aggregate Industries and not an employee, this individual did not follow Aggregate Industries' spill response procedure for when a spill occurs. All employees and Independent Haulers are required to contact Aggregate Industries' Transportation Manager to seek guidance on the clean-up of spills, as well as to fill out a detailed Spill Report form. The Transportation Manager has been requested to review proper procedures when reporting and cleaning up a spill.

Wastes Disposal Location:

Gowan Construction will be disposing of the material. Please contact Curt with Gowan Construction @ (701) 739-1674.

Other Agencies Involved:

Updates

Date: 7/11/2019 ***Status:*** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release of hydraulic fluid was not contained. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 5/11/2020 ***Status:*** Correspondence - No Action Required

Author: Sues, Bill

Notes:

Spoke with both Aggregate Industries and Gowan Construction. The spill occurred within a mobile batch plant. The material was scraped up and transport to Gowan's main facility where it was land farmed. The batch plant has since been reclaimed. Due to the size and nature of this incident, no further action is warranted.

Updated Volume: None at the time of this update