

# *General Environmental Incident Summary*

**Incident:** 9240      **Notice:** 9/20/2019    1100    **Occurred:** 9/19/2019    1600  
**DEM Incident No:**      **No Further Action:**

**Responsible Party:**    Straight Line Directional LLC  
**County:**                    McKenzie  
**Twp Rng Sec Qtr:**        149    97    13  
**Lat Long + Method:**    47.71812    -103.03920    Interpolation from map  
**Location Description:** 114 th M Ave NW south of Beaver Creek Rd. South of Hwy 23  
**Submitted By Info:**      Ryan Olsen  
  2865 Finley St  
  Lincoln ND  
**Received By Info:**        Ryan Olsen  
**Contact Info:**             Ryan Olsen  
  5209 Sunlight Drive  
  Bismarck ND 58504  
**Affected Medium:**        03 - soil  
**Near. Occupied Bldg:**  
**Type of Incident:**         Bentonite mud release  
**Release Contained:**      Yes  
**Reported to NRC:**         Unknown  
**Contaminant:**             Bentonite  
**Volume of Release:**  
**Duration of Release:**  
**Agriculture Related:**     No  
**EPA Extremely  
Hazardous Substance:** Unknown  
**Number of Fatalities:**  
**Number of Injuries:**  
**Cause of Incident:**  
Saturated Ground Condition  
**Risk Evaluation:**  
No Immediate Risk  
**Potential Env. Impacts:**  
No Environmental Impacts  
**Action Taken/Planned:**  
Contained with silt fence, washed down and cleaned up with a vac truck  
**Wastes Disposal Location:**  
**Other Agencies Involved:**

## **Updates**

---

**Date:** 9/20/2019      **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Notes:**

Release during drilling activities. Follow up is required.

**Updated Volume:** None at the time of this update

---

**Date:** 10/21/2019      **Status:** Inspection - No Action Required

**Author:** Suess, Bill

**Notes:**

Visited the site on 10/16/2019. Bentonite has been cleaned up. Vegetation recovery will be part of the pipeline reclamation. No further action is warranted.

**Updated Volume:** None at the time of this update