

General Environmental Incident Summary

Incident: 9246 **Notice:** 9/24/2019 1202 **Occurred:** 9/22/2019 1100

DEM Incident No:

No Further Action:

Responsible Party: Recycling Center of North Dakota

County: Stutsman

Twp Rng Sec Qtr: 140 64 36

Lat Long + Method: 46.89916 -98.70288 Interpolation from map

Location Description: In the alley just North of 10th Street SE between 4th and 5th Ave

Submitted By Info: Ralph Friebel
PO Box 1805
Jamestown ND 58402

Received By Info:

Contact Info: Ralph Friebel
PO Box 1805
Jamestown ND 58402

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Hydraulic hose burst

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Hydraulic Fluid

Volume of Release: 30 gallons

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

A hydraulic hose on a recycling truck burst

Risk Evaluation:

None

Potential Env. Impacts:

Once the gravel is removed and replaced there should be no longterm impact from spill

Action Taken/Planned:

City fire department and street department arrived and placed sand in area to contain spill and soak up fluid. A company in Jamestown that deals with clean up has been contacted and is going to clean up the spill. It will involve removing gravel from the alley and replacing it with new gravel

Wastes Disposal Location:

TBD

Other Agencies Involved:

Local Fire Department, City of Jamestown

Updates

Date: 9/24/2019 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release was not contained. Further follow-up will be made with responsible party on clean up efforts.

Updated Volume: None at the time of this update

Date: 10/21/2019 **Status:** Inspection - No Action Required

Author: Washek, Sandi

Notes:

Arrived onsite the weather was overcast and raining.

The area of impact is located in the alley between 4th and 5th Streets . The area had been scraped up and new sand and gravel had been placed down around the west driveway concrete pad. There is a very small puddle with a little sheen on the puddle (puddle is about 12" by 12'). No other visible staining to sheen could be seen in the alley. No additional follow-up needed.

Updated Volume: None at the time of this update