## General Environmental Incident Summary

**Incident:** 9314 **Notice:** 11/13/2019 **Occurred:** 11/6/2019 1200

DEM Incident No: No Further Action: ✓

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY

County: McKenzie
Twp Rng Sec Qtr: 153 95 25

Lat Long + Method: 48.03909 -102.84420 Navigation quality GPS

Location Description: Archer 14-25 TFH wellpad.

Submitted By Info: Kelsy Waggaman

11090 30th Street SW

Dickinson ND

Received By Info:

Contact Info:

925 N Eldridge

Houston TX

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Chemical spill

Release Contained: No
Reported to NRC: Unknown
Contaminant: Anti-freeze

Volume of Release: 0.12 barrels

**Duration of Release:** 

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: NoNumber of Fatalities: 0Number of Injuries: 0

Cause of Incident:

The 2" radiator hose broke loose and caused a 4'x10' spill.

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

Replaced the radiator hose. Contaminated soil was dug up.

Wastes Disposal Location:

**TBD** 

Other Agencies Involved:

## **Updates**

Date: 11/14/2019 Status: Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 0.12 barrels of anti-freeze was released on a well site. More follow-up

needed.

Updated Volume: None at the time of this update

Date: 11/18/2019 Status: Inspection - No Action Required

Author: Schmitt, Bryan

Notes:

Inspection Date: 11/13/2019

Time: 4:00pm CT Temp: 28F

Walked throughout the well pad and did not see any remaining impacts. Anti-freeze was not found.

Updated Volume: None at the time of this update