# General Environmental Incident Summary

**Incident:** 9316 **Notice:** 11/14/2019 **Occurred:** 11/11/2019 0800

DEM Incident No: No Further Action: ✓

Responsible Party: SMF Logistics, LLC

County: Dunn

**Twp Rng Sec Qtr:** 147 97 12

Lat Long + Method: 47.56091 -102.97640 Navigation quality GPS

Location Description: LK-BICE-147-97-1201H-4

Submitted By Info: Al Markegard

**Director of Crude Operations** 

11074 32E ST SW Dickinson ND 58601

Received By Info:

Contact Info: Al Markegard

11074 32E ST SW Dickinson ND 58601

Affected Medium: 09 - other

Near. Occupied Bldg:

Type of Incident: tanker valve leaking

Release Contained: Yes
Reported to NRC: Unknown

Contaminant: ND sweet crude oil

Volume of Release: 5 gallons

**Duration of Release:** 

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance:NoNumber of Fatalities:0Number of Injuries:0

Cause of Incident:

once loaded, the tanker valve leaked droplets of oil from well site onto the lease road

Risk Evaluation:

none

### Potential Env. Impacts:

none - oil was primarily leaked onto the snow pack

## Action Taken/Planned:

Cleanup company was called to the location, SM Fencing & Energy Services. Leaked oil was cleaned up and removed.

### Wastes Disposal Location:

Horizon Oilfield Services, Killdeer, ND

### Other Agencies Involved:

## **Updates**

Date: 11/14/2019 Status: Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 5 gallons of crude was released onto the lease road. More follow-up needed.

Updated Volume: None at the time of this update

Date: 11/21/2019 Status: Inspection - No Action Required

Author: O'Gorman, Brian

#### Notes:

Arrived on location at 13:25. 32 degrees F, Sunny, West wind 5-15 mph. Observed the site and took photos. Did not notice any hydrocarbon stained surface soils or lease road gravel on or near the well pad. No further follow-up needed at this time. Photos added to the incident folder.

Updated Volume: None at the time of this update