

General Environmental Incident Summary

Incident: 9318

Notice: 11/15/2019

Occurred: 11/13/2019 1800

DEM Incident No:

No Further Action:

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY

County: Dunn

Twp Rng Sec Qtr: 147 95 26

Lat Long + Method: 47.53010 -102.75030 Navigation quality GPS

Location Description: CCU BURNER 1-1-26MBH facility.

Submitted By Info: Kelsy Waggaman
11090 30th Street SW
Dickinson ND

Received By Info:

Contact Info:
925 N Eldridge
Houston TX

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Spill

Release Contained: No

Reported to NRC: No

Contaminant: Hydraulic oil

Volume of Release: 0.89 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Swab rig-hydraulic hose failed.

Risk Evaluation:

None.

Potential Env. Impacts:

None.

Action Taken/Planned:

Hose will be replaced and spill will be cleaned up.

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 11/19/2019 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, there was a release of hydraulic fluid on location. Further follow up is needed.

Updated Volume: None at the time of this update

Date: 11/21/2019 **Status:** Inspection - No Action Required

Author: O'Gorman, Brian

Notes:

Arrived on location at 13:21. 36 degrees F, Sunny, West wind 5-15 mph. Met with the operator of the swab rig and a representative of Conoco Philips. The swab rig rep led me to the location of the release. The location was approximately 15' in diameter and was located approximately 20' south of the west pump jack. The scoria in the area appeared un-impacted from hydraulic fluid. No further follow-up needed at this time. Photos taken and added to the incident folder.

Updated Volume: None at the time of this update