

# General Environmental Incident Summary

**Incident:** 9407

**Notice:** 2/14/2020

**Occurred:** 2/14/2020 1500

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** ConocoPhillips

**County:** Dunn

**Twp Rng Sec Qtr:** 147 95 19

**Lat Long + Method:** 47.53221 -102.82360 Navigation quality GPS

**Location Description:** Well Location: CCU Meriwether 44-19 MBH

**Submitted By Info:** Kelsy Waggaman  
11090 30th Street SW  
Dickinson ND

**Received By Info:**

**Contact Info:**

925 N Eldridge  
Houston ND

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:**

**Type of Incident:** Pump Leak

**Release Contained:** No

**Reported to NRC:** No

**Contaminant:** Transmission Fluid

**Volume of Release:** 1 gallons

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely**

**Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

The Hydraulic pump on the rig cracked and leaked 1 Gal. of transmission fluid to the ground.

**Risk Evaluation:**

None.

**Potential Env. Impacts:**

Transmission fluid to facility soil.

**Action Taken/Planned:**

Site is secure and spill is contained. The spill will be cleaned up on location using a shovel and disposed of by the contract company, Ranger.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

## **Updates**

---

**Date:** 2/14/2020      **Status:** Reviewed - No Action Required

**Author:** Suess, Bill

**Notes:**

Due to the size and nature of the incident, no follow-up is required.

**Updated Volume:** None at the time of this update