

# *Oil Field Environmental Incident Summary*

**Incident:** 20170721111859      **Notice:** 7/21/2017    11:18    **Occurred:** 7/20/2017    14:00

**Responsible Party:** WESCO OPERATING, INC.

**Well Operator:** WESCO OPERATING, INC.

**Well Name:** MINNIE OLSEN    2-18

**Field Name:** BICENTENNIAL

**Well File #:** 5975

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 145   103   18

**Location Description:** Within facility containment

**Submitted By:** Scott Kerr

**Received By:**

**Contact Info:** Scott Kerr  
PO BOX 1650  
120 S. DURBIN STREET  
CASPER WY 82602

**Affected Medium:** Well/Facility Soil

**General Land Use:** Pasture

**Near. Occupied Bldg:** 2.5 Mile

**Nearest Water Well:** 2.5 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	7	Barrels	6	Barrels	6	barrels

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 7/21/2017

**Written Report Recd:** 8/1/2017

**Risk Evaluation:**

None

**Areal Extent:**

Contained within building and berm

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Pipe connection failed within building. Majority of fluids contained within in building sump. Fluids were recovered and placed into produced water system. Pipe connection replaced.

**Wastes Disposal Location:**

Recovered fluids were placed into produced water tank.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 7/24/2017      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update