Oil Field Environmental Incident Summary

Incident: 20171113091632 Notice: 11/13/2017 09:16 Occurred: 11/12/2017 12:56

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: LINCOLN HILLS 41-18H

Field Name: KILLDEER Well File #: 17987

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 145 94 18 NE NE

Location Description:

Submitted By: Josey Adams

Received By:

Contact Info: Josey Adams

600 N. DAIRY ASHFORD

HOUSTON TX 77079

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 3000 Feet Nearest Water Well: 3000 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits70Barrels70Barrels18barrels

Brine Other

Oil

Oth Rel. Contaminant: Leak from valve on recycle that resulted in 70 BBL spill. Spill maintained in

dike

Date Inspected:

Clean Up Concluded: 3/30/2018 Written Report Recd: 7/12/2018

Risk Evaluation:Spill to the environment

Areal Extent:

Spill stayed inside tank dike **Potential Env. Impacts:**

Spill stayed inside tank dike. Spill to the ground

Action Taken/Planned:

Valve was shut tight.

Wastes Disposal Location:

Tervita Landfill

Other Agencies Involved:

Updates

Date: 11/14/2017 Status: Reviewed - No Action Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

This incident report looks to be a duplicate. Please continue to incident #20171113091633.

Updated Volumes and Contaminant None at the time of this update