Oil Field Environmental Incident Summary

Incident: 20180228082354 Notice: 2/28/2018 08:23 Occurred: 2/27/2018 16:30

Responsible Party: DENBURY ONSHORE, LLC
Well Operator: DENBURY ONSHORE, LLC

Well Name: CEDAR CREEK UNIT 8B 32-11A-18H

Field Name: CEDAR CREEK

Well File #: 3103

Facility ID #:

County: BOWMAN
Twp Rng Sec Qtr: 130 107 11

Location Description: 200 feet east of location

Submitted By: David Hill

Received By:

Contact Info: Jeff Varner

5320 LEGACY DR

PLANO TX 75024-3127

Affected Medium: Topsoil
General Land Use: Pasture

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Other Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 3/22/2018
Written Report Recd: 4/4/2018

Risk Evaluation:

None

Areal Extent:

200 feet east of location **Potential Env. Impacts:**

None

Action Taken/Planned:

Isolated injection line. Will scoop up impacted snow and excavate impacted soil.

Wastes Disposal Location:

TBD

Other Agencies Involved:

BLM

Updates

Date: 2/28/2018 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release of 10 barrels of brine was not contained to the well pad. Further follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 2/28/2018 Status: Inspection No Further Action: ✓

Author: Crowdus, Kory

Notes:

On location 2/28/2018, at 12:04pm. Release is off pad to the east. Snow and some soil are being scraped at the time of inspection. Area is approximately 60x10 yards. Material is being placed in a metal bin, which was full during inspection, the rest is being stockpiled on location. Further follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 9/4/2018 Status: Inspection No Further Action: ✓

Author: Martin, Russell

Notes:

8/23/2018 at 16:31, on location. Metal bin described in previous inspection is gone. Walked east edge of site, vegetation appears uniform, no barren areas within incident area. No further follow-up required at this time.

Updated Volumes and Contaminant None at the time of this update