## Oil Field Environmental Incident Summary

Incident: 20180316083209 Notice: 3/16/2018 08:32 Occurred: 3/15/2018 10:20

Responsible Party: SCOUT ENERGY MANAGEMENT LLC
Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: HOFLAND 5-24H

Field Name: WILEY Well File #: 15217

Facility ID #:

County: BOTTINEAU

*Twp Rng Sec Qtr:* 161 82 24 NE NE

Location Description:

Submitted By: REBECCA Sample

Received By:

Contact Info: Beki Sample

4901 LBJ FREEWAY, STE 300

DALLAS TX 75244

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.5 Mile Nearest Water Well: 0.5 Mile

Type of Incident: Stuffing Box Leak Release Contained: Yes - Within Dike

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 Barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Env. Impacts:

N/A

Action Taken/Planned:

A vac truck was dispatched and sucked up the water in the dike

Wastes Disposal Location:

Water will be put into storage tank. Contaminated soil will be hauled to Indian Hills disposal when ground thaws.

Other Agencies Involved:

## **Updates**

Date: 3/16/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Schiermeister, Robin

Notes:

Release, due to a stuffing box leak, according to the report remained on the well pad. NDIC retains

oversight.

Updated Volumes and Contaminant None at the time of this update