

# Oil Field Environmental Incident Summary

**Incident:** 20180510105141      **Notice:** 5/10/2018    10:51      **Occurred:** 5/9/2018    09:15

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** BAILEY 1-24H

**Field Name:** PERSHING

**Well File #:** 17770

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 150 97 24

**Location Description:**

**Submitted By:** Michael Harris

**Received By:**

**Contact Info:** Michael Harris  
PO BOX 268870  
OKLAHOMA CITY OK 73126

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained:** Unknown

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

N/A

**Wastes Disposal Location:**

**Other Agencies Involved:**

## **Updates**

---

**Date:** 5/10/2018      **Status:** Reviewed - Follow-up Required

**No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 5/21/2018      **Status:** Inspection

**No Further Action:**

**Author:** Schiermeister, Robin

**Notes:**

Arrived on site at 10:48 on 5-15-2018. It was sunny with temperatures in the 70's. Walked around the perimeter of the well pad and could not find any evidence a fire leaving the pad. No further follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update