## Oil Field Environmental Incident Summary

Incident: 20180905175623 Notice: 9/5/2018 17:56 Occurred: 9/5/2018 15:45

Responsible Party: SCOUT ENERGY MANAGEMENT LLC
Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: MOSSER 2-22

Field Name: T. R. Well File #: 6659

Facility ID #:

County: BILLINGS

Twp Rng Sec Qtr: 141 101 22 SE SE

Location Description:

Submitted By: Beki Sample

Received By:

Contact Info: Beki SAMPLE

4901 LBJ FREEWAY, STE 300

DALLAS TX 75244

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 2 Mile
Nearest Water Well: 3000 Feet
Type of Incident: Tank Overflow
Release Contained: Yes - Within Dike

Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits5Barrels5Barrels5barrels

Brine Other

Oil

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 9/7/2018
Written Report Recd: 4/25/2019

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Env. Impacts:

N/A

Action Taken/Planned:

Vac truck was dispatched to recover oil. Transfer pump will be repaired or replaced. Contaminated soil and rock will be cleaned up and disposed of and replaced with fresh rock and soil.

## Wastes Disposal Location:

Oil will be recovered and returned to storage tank. Contaminated soil and rock will be disposed of at Indian Hills Disposal

Other Agencies Involved:

## **Updates**

Date: 9/6/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Schiermeister, Robin

Notes:

Release, due to a tank overflow, remained on site. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update