# Oil Field Environmental Incident Summary

Responsible Party: Frickey Investment Management Company

Well Operator:NORTON FRICKEYWell Name:STATE 1-16Field Name:WHISKEY JOE

**Well File #:** 7120

Facility ID #:

County: BILLINGS

Twp Rng Sec Qtr: 141 100 16 NE SE

Location Description: Soaked through treter dike onto grass below treater.

Submitted By: Zach Dworshak

Received By:

Contact Info: Charmaine Frickey

940 WADSWORTH BLVD LAKEWOOD CO 80215

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Treater Leak

Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 10 Barrels
Brine 5 Barrels

Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

N/A

Areal Extent: 40x60 feet

Potential Env. Impacts:

N/A

#### Action Taken/Planned:

Spill was contained within treater dike. James Oil Well crew was called out immediately to start cleaning up mess. State hand, Nicole Ewoniuk was notified.

### Wastes Disposal Location:

In water tank on location.

#### Other Agencies Involved:

N/A

## **Updates**

Date: 9/7/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Schiermeister, Robin

Notes:

Release, due to a treater leak, remained on site. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update