Oil Field Environmental Incident Summary

Incident: 20180909155720 Notice: 9/9/2018 15:57 Occurred: 9/8/2018 14:30

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC
Well Name: Beaver Lodge Silurian Unit Central Facility

Field Name: BEAVER LODGE

Well File #:

Facility ID #: 401513-01
County: WILLIAMS

Twp Rng Sec Qtr: 156 95 31 SW NW

Location Description:

Submitted By: Alex Beach

Received By:

Contact Info: Troy Brunsell

1501 MCKINNEY

HOUSTON TX 77010

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.3 Mile
Nearest Water Well: 0.3 Mile
Type of Incident: Other
Release Contained: No
Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 18 Gallons

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd:

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

total impacted area, 400' x 60' (80' x 40' off location)

Potential Env. Impacts:

The release impacted an approximate 80' x 40' area, off location.

Action Taken/Planned:

The Hess land department will notify the landowner. The Hess Environmental Department will coordinate with an environmental contractor to remediate the impacted areas.

Wastes Disposal Location:

All recovered waste will be disposed at an approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 9/10/2018 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: O'Gorman, Brian

Notes:

According to the report, 18 gallons of 'other' was released and not contained. Further follow-up

needed.

Updated Volumes and Contaminant None at the time of this update

Date: 9/13/2018 Status: Inspection No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 17:13 9/13/2018.

No sign of contamination at the described location. Contact responsible party on exact location.

More follow-up necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 8/6/2019 Status: Inspection No Further Action: ✓

Author: O'Gorman, Brian

Notes:

Arrived on location at 13:13. Observed the incident area and took photos. It appeared the area of concern had been remediated appropriately with a wheat crop, appearing healthy and consistent in the field to the south. No further follow-up needed at this time. Photos added to the incident folder.

Updated Volumes and Contaminant None at the time of this update