

Oil Field Environmental Incident Summary

Incident: 20180913155108 **Notice:** 9/13/2018 15:51 **Occurred:** 9/12/2018 18:30

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: KERMIT 1-32H

Field Name: PERSHING

Well File #: 16792

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 150 96 32 SE SW

Location Description: MSO was bringing on a well and there was condensate in the line leading to a oil to flare event. No fire occurred.

Submitted By: Josey Adams

Received By:

Contact Info:
Josey Adams
600 N. DAIRY ASHFORD
HOUSTON TX 77079

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1 Mile

Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.3	Barrels	0.3	Barrels	0.28	barrels

Brine

Other

Oth Rel. Contaminant: Oil to flare event that affected area on and off pad.

Date Inspected:

Clean Up Concluded: 9/27/2018

Written Report Recd: 10/9/2018

Risk Evaluation:

Oil to the ground

Areal Extent:

18' X 70' by .0625" equaling .28 bbl. of oil

Potential Env. Impacts:

Oil to the groun

Action Taken/Planned:

Workorder created to clean up contaminated area on and off pad and to drain the lines.

Wastes Disposal Location:

Tervita Landfill

Other Agencies Involved:

Updates

Date: 9/14/2018 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a valve/piping connection leak was not contained to the well pad, according to the report. Further follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Date: 9/18/2018 **Status:** Inspection **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 9/18/2018, at 1:01pm. Release was off location to the west of flare. There is light oil staining in the pasture land approximately 150x10ft. Further follow-up is required to check on vegetation growth in the area.

Updated Volumes and Contaminant None at the time of this update

Date: 6/11/2019 **Status:** Inspection **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 6/11/2019, at 2:34pm. West of the flare there is a bare area near the fence line approximately 10x5 ft. It appears some soil was removed from this area during cleanup. Will need to contact company to bring in soil and seed area. Further follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 5/5/2020 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 5/5/2020, at 2:20pm. There is still an area off location approximately 10 ft x 5 ft with limited to no growth. Company will be contacted to address area. Follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 8/3/2020 **Status:** Inspection - No Action Required **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 8/3/2020, at 3:38pm. Area has been seeded and is showing growth since last inspection. No further follow-up is required.

Updated Volumes and Contaminant None at the time of this update