Oil Field Environmental Incident Summary

Incident: 20181101142358 Notice: 11/1/2018 14:23 Occurred: 10/30/2018 12:30

Responsible Party: Crescent Point Energy, US Corp

Well Operator: CRESCENT POINT ENERGY U.S. CORP.

Well Name:
Field Name:
Well File #:
Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 157 100 26 NW NW

Location Description: 48.40025, -103.5788 On pipeline ROW in field SW of NJOS 157-100-26D-

35-1H well location.

Submitted By: Chris Martinez

Received By:

Contact Info: Chris Martinez

555 17th Street Suite 1800

Denver CO 80202

Affected Medium: Topsoil
General Land Use: Pasture

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained: Yes - On Pipeline ROW

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels 5 Barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd:

Risk Evaluation:

No immediate risk due to small volume and remote location

Areal Extent:

Potential Env. Impacts:

No impacts due to small volume and remote location

Action Taken/Planned:

Line was shut in, valve was replaced and placed back in service. Approximately 8 cubic yards of material was removed and sent to disposal. Soil samples were taken after excavation and results are pending.

Wastes Disposal Location:

Secure 13 Mile Landfill

Other Agencies Involved:

Updates

Date: 11/1/2018 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release of 5 barrels of production water was not contained.

Further follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 11/1/2018 Status: Correspondence No Further Action: ✓

Author: DeVries, Taylor

Notes:

This is a duplicate report. The report number for this spill is #5893 and can be found in the General Environmental Incident Database.

Updated Volumes and Contaminant None at the time of this update