## Oil Field Environmental Incident Summary

Incident: 20190218132520 Notice: 2/18/2019 13:25 Occurred: 2/16/2019 14:00

Responsible Party:HESS BAKKEN INVESTMENTS II, LLCWell Operator:HESS BAKKEN INVESTMENTS II, LLCWell Name:BB-SIVERTSON- LN-151-95-1719H-1

Field Name: BLUE BUTTES

**Well File #:** 30084

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 151 95 17

Location Description:

Submitted By: Troy Brunsell

Received By:

Contact Info: Ron Brown

1501 MCKINNEY

HOUSTON TX 77010

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 1 Mile
Nearest Water Well: 1 Mile
Type of Incident: Tank Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 Barrels 10 barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 2/20/2019 Written Report Recd: 3/15/2019

Risk Evaluation:

No immediate risk to report at this time

Areal Extent:

Potential Env. Impacts:

No potential environmental impacts to report at this time

Action Taken/Planned:

Upon discovery of the leak the remaining fluid was transferred to another tank, removing the failed tank from service. The use of a vac truck and a mud pump were used to recover the remaining fluid around the area of concern on location.

Wastes Disposal Location:

Approved facility

Other Agencies Involved:

## **Updates**

Date: 2/19/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained on the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update