

Oil Field Environmental Incident Summary

Incident: 20190311185838 **Notice:** 3/11/2019 18:58 **Occurred:** 3/11/2019 04:00

Responsible Party: CRESCENT POINT ENERGY U.S. CORP.
Well Operator: CRESCENT POINT ENERGY U.S. CORP.
Well Name: CPEUSC BERNER 2-19-18-157N-99W MBH
Field Name: LONE TREE LAKE
Well File #: 33688
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 157 99 19
Location Description:
Submitted By: Chris Martinez
Received By:
Contact Info: Chris Martinez
 555 17TH STREET, SUITE 1800
 DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Tank Overflow
Release Contained: Yes - On Constructed Well Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	25	Barrels	25	Barrels		
Other						

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

Low risk - soil was frozen which kept brine from penetrating.

Areal Extent:
Potential Env. Impacts:

No potential environmental impacts due to quick removal.

Action Taken/Planned:

- 1) Shut valves after bringing fluids in from the uprights to prevent continuous gravity feed.
- 2) Educate new employees on operation of dewatering unit and plumbing/valves within dewatering unit.

Wastes Disposal Location:
 Will be used on-site in drilling fluid.

Other Agencies Involved:

Updates

Date: 3/12/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to tank overflow remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update