

Oil Field Environmental Incident Summary

Incident: 20190704170907 **Notice:** 7/4/2019 17:09 **Occurred:** 7/4/2019 02:00

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: RAVIN CTB

Field Name: DIMMICK LAKE

Well File #: 34178

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 150 97 1

Location Description: 40' x 100' extending out from flare

Submitted By: Nate Sem

Received By:

Contact Info: Tim Butts
9097 78th St NW
OKLAHOMA CITY OK 73126

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Fire

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant: No released fluid

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

burnt grass off location

Areal Extent:

40' x 100' outside the fence

Potential Env. Impacts:

impacted vegetation

Action Taken/Planned:

Fire was extinguished immediately by personnel.

Wastes Disposal Location:

none

Other Agencies Involved:

Updates

Date: 7/5/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: DeVries, Taylor

Notes:

According to the incident report, the fire was not contained to the well pad. Further follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 8/5/2019 **Status:** Inspection

No Further Action:

Author: Martin, Russell

Notes:

8/1/2019 at 11:36, on location. Burnt vegetation visible by SE corner of wellpad, next to large flare. New vegetation starting to grow, no staining visible within scorched area. No further follow-up needed.

Updated Volumes and Contaminant None at the time of this update