Oil Field Environmental Incident Summary

Incident: 20191108121921 Notice: 11/8/2019 12:19 Occurred: 11/7/2019 11:16

Responsible Party: SCOUT ENERGY MANAGEMENT LLC
Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: NELSON 3 1
Field Name: INDIAN HILL

Well File #: 10723

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 102 12 NE NE

Location Description:

Submitted By: Beki Sample

Received By:

Contact Info: Beki Sample

4901 LBJ FREEWAY, STE 300

DALLAS TX 75244

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 1749 FeetNearest Water Well: 1749 FeetType of Incident: Treater Popoff

Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 40 Barrels 38 Barrels

Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

N/A

Areal Extent:

2' x 15' of a very fine mist left the south side of the location.

Potential Env. Impacts:

N/A

Action Taken/Planned:

Well was shut in. A vac truck was dispatched to recover oil. Once the problem is resolved as to why the pop-off blew, appropriate actions will be taken.

Wastes Disposal Location:

Indian Hills Disposal

Other Agencies Involved:

Updates

Date: 11/8/2019 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report the release of 40 barrels of crude oil was not contained to the well

pad. Further follow up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 11/18/2019 Status: Inspection - More Follow-up Required No Further Action: ✓

Author: Schmitt, Bryan

Notes:

Inspection Date: 11/14/2019

Time: 12:10 pm CT

Temp: 38F

Oil spill occurred south of the treater. Impacted soil was observed off pad and snow covered a portion of the spill area. I did not see any oil staining on vegetation approximately 30 feet to the south. Pictures taken.

Updated Volumes and Contaminant None at the time of this update

Date: 7/31/2020 Status: Inspection - No Action Required No Further Action: ✓

Author: Martin, Russell

Notes:

7/16/2020 at 13:51, on location. Walked site, vegetation off pad to the south appears healthy, no visible staining from the incident appears to remain on the wellpad. No further-follow-up needed.

Updated Volumes and Contaminant None at the time of this update