

Oil Field Environmental Incident Summary

Incident: 20200216132900 **Notice:** 2/16/2020 13:29 **Occurred:** 2/16/2020 02:00

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: MUSKRAT 150-94-04B-09H

Field Name: SPOTTED HORN

Well File #: 29528

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 151 94 33 SE SW

Location Description:

Submitted By: Joey Sheeley

Received By:

Contact Info: Josh Ruffo
US BANK TOWER
950 17TH ST STE 2200
DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	30	Barrels				
--------------	----	---------	--	--	--	--

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None.

Areal Extent:

N/A

Potential Env. Impacts:

None.

Action Taken/Planned:

The valve was closed and a clean-up crew was dispatched.

Wastes Disposal Location:

Approved disposal facility

Other Agencies Involved:

BLM, MHA Energy, TAT Environmental

Updates

Date: 2/18/2020

Status: Reviewed - Assigned to Other Agency

No Further Action:

Author: Suess, Bill

Notes:

Incident was contained on an E & P exempt facility and was located on the Ft Berthold Reservation. The Tribe and NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update