

Oil Field Environmental Incident Summary

Incident: 20200727121042 **Notice:** 7/27/2020 12:10 **Occurred:** 7/26/2020 01:00

Responsible Party: Oasis Petroleum North America LLC
Well Operator: OASIS PETROLEUM NORTH AMERICA LLC
Well Name: BERRY 5493 11-6H
Field Name: ROBINSON LAKE
Well File #: 18857
Facility ID #:
County: MOUNTRAIL
Twp Rng Sec Qtr: 154 93 6 LO 4
Location Description:
Submitted By: Dustin Anderson
Received By:
Contact Info: Dustin Anderson
1001 FANNIN STE 1500
HOUSTON TX 77002

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels	38	Barrels		

Other

Oth Rel. Contaminant: Produced water

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Contained within the dikes on the well pad

Areal Extent:

80 feet wide by 130 feet long

Potential Env. Impacts:

Low - impacted location material is being removed for off-site disposal

Action Taken/Planned:

Increase site security

Wastes Disposal Location:

R360

Other Agencies Involved:

Updates

Date: 7/27/2020 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Lund, Dylan

Notes:

According to the incident report, the release was confined to the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update