

# *Oil Field Environmental Incident Summary*

**Incident:** 20201222075634      **Notice:** 12/22/2020 07:56      **Occurred:** 12/21/2020 10:15

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC  
**Well Operator:** SCOUT ENERGY MANAGEMENT LLC  
**Well Name:** FRYBURG HEATH-MADISON UNIT G-805HR  
**Field Name:** FRYBURG  
**Well File #:** 13497  
**Facility ID #:**  
**County:** BILLINGS  
**Twp Rng Sec Qtr:** 139 101 14 SW SW  
**Location Description:**  
**Submitted By:** Beki Sample  
**Received By:**  
**Contact Info:** Beki Sample

4901 LBJ FREEWAY, STE 300  
DALLAS TX 75244

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Well/Facility Site  
**Near. Occupied Bldg:** 0.3 Mile  
**Nearest Water Well:** 0.3 Mile  
**Type of Incident:** Tank Leak  
**Release Contained:** Yes - Within Dike  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	40	Barrels	35	Barrels		
<b>Other</b>						

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

N/A

**Areal Extent:**

N/A

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

A vac truck was dispatched to recover the leaked water. A new tank will be installed

**Wastes Disposal Location:**

Produced water was taken to the disposal at the Fryburg SWD #2

**Other Agencies Involved:**

## **Updates**

---

**Date:** 12/22/2020    **Status:** Reviewed - Assigned to Other Agency    **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release was contained on location. NDIC takes oversight.

**Updated Volumes and Contaminant**    None at the time of this update