

General Environmental Incident Summary

Incident: 5288

Notice: 12/16/2016

Occurred: 12/16/2016

DEM Incident No:

No Further Action:

Responsible Party: Fuel Force

County: Mountrail

Twp Rng Sec Qtr: 156 91 28

Lat Long + Method: 48.30688 -102.38750 Interpolation from map

Location Description: 301 12th ave SE Fuel Force. Stanley ND

Submitted By Info: Tina Stoddard
PO Box 338
Stanley ND 58784

Received By Info:

Contact Info:

301 12th ave SE
Stanley ND 58784

Affected Medium: 09 - other

Near. Occupied Bldg: 300 Feet

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Gasoline

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Fuel was put into the wrong tank due to being mislabeled, and there was an overflow due to that.

Risk Evaluation:

None

Potential Env. Impacts:

none

Action Taken/Planned:

Sand, and floor dry by the fire department

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 12/17/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, an unknown amount of gasoline was released at the Fuel Force gas station. Report also states that the fire department took action using sand and Floor Dry. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 1/23/2017 **Status:** Correspondence

Author: Schiermeister, Robin

Notes:

Talked to the Fuel Force representative. The representative ensured NDDoH that the contamination has been thoroughly cleaned up with sand and floor dry. The tank that was contaminated with unleaded gasoline was a premium line. The tank has been relabeled unleaded gasoline until the product is all used. No further follow up is necessary.

Updated Volume: None at the time of this update