General Environmental Incident Summary

Incident: 5466 Notice: 7/21/2017 0821 Occurred: 7/20/2017 1620

DEM Incident No: No Further Action:

✓

Responsible Party:MagellanCounty:Grand ForksTwp Rng Sec Qtr:152 50 32

Lat Long + Method: 47.93312 -97.08409 Address matching

Location Description: Magellan Midstream Grand Forks Terminal, 3930 Gateway Drive, Grand

Forks, ND

Submitted By Info: Trena Hallback

Magellan - Environmental Specialist

One Williams Center

OTC-8

Tulsa OK 74172

Received By Info:

Contact Info: Trena Hallback

3930 Gateway Drive

Grand Forks ND 58201

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Hose leak
Release Contained: Yes
Reported to NRC: Unknown

Reported to NRC: Unknown
Contaminant: gasoline
Volume of Release: 20 gallons

Duration of Release: 2 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0 **Number of Injuries:** 0

Cause of Incident:

After a drain up operation, the vac truck operator failed to place the cap on the end of the hose. This resulted in a release of 20 gallons into the earthen dike.

Risk Evaluation:

none

Potential Env. Impacts:

none

Action Taken/Planned:

The impacted soil within the earthen dike was excavated, places into drums, and is awaiting

Wastes Disposal Location:

Landfill

Other Agencies Involved:

----- ..g------ -----

Updates

Date: 7/21/2017 Status: Reviewed - No Action Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill occurred within an earthen dike, so impact of

surrounding areas is unlikely. No follow-up is necessary.

Updated Volume: None at the time of this update