## General Environmental Incident Summary

*Incident:* 5601 *Notice:* 1/5/2018 *Occurred:* 1/5/2018 1700

DEM Incident No: No Further Action: ✓

Responsible Party: Aspen Air Corp.
County: McKenzie

Twp Rng Sec Qtr: 151 102 22 SW SW SW

Lat Long + Method: 47.87720 -103.73070 Navigation quality GPS

Location Description: North West from Alexander ND, 4 miles west down highway 200 off of

Highway 85

Submitted By Info: Kenneth Morse

1524 Lockwood Rd Billings MT 59101

Received By Info:

**Contact Info:** 

1524 Lockwood Rd.

Billings MT

Affected Medium: 01 - air

Near. Occupied Bldg:

Type of Incident: Vehicle Accident

Release Contained: Yes
Reported to NRC: Unknown

Contaminant: Liquid Nitrogen

Volume of Release: 30 gallons
Duration of Release: 2 hours
Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: No

Number of Fatalities: Number of Injuries: Cause of Incident: Semi truck roll over Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

Evaporation to atmosphere

Wastes Disposal Location:

Other Agencies Involved:

Friday, October 2, 2020 Page 1 of 2

## **Updates**

Date: 1/5/2018 Status: Reviewed - Assigned to NDDEQ Division

Author: O'Gorman, Brian

Notes:

According to the report, 30 gallons of liquid nitrogen were released, due to a truck accident. Report

forwarded to Air Quality for further follow-up.

Updated Volume: None at the time of this update

Date: 1/10/2018 Status: Reviewed - No Action Required

Author: Martin, Russell

Notes:

Received pictures of incident from first responders. Based on location being a harvested field and volume of only 30 gallons lost, no action required. Added pictures to incident folder.

Updated Volume: None at the time of this update

Date: 1/10/2018 Status: Inspection

Author: Sandvick, Duane

Notes:

Date: 1-10-2018 Arrival time: 11:22 am CST

Weather conditions: 5 degrees Fahrenheit, cloudy, snowing, blowing snow with north wind at 20 mph

While driving past the accident site, there were no visible signs of the accident in the snow covered Hwy 200 ditch. No further action is required. No photos taken.

Updated Volume: None at the time of this update

Friday, October 2, 2020 Page 2 of 2