

General Environmental Incident Summary

Incident: 5659 **Notice:** 3/15/2018 2125 **Occurred:** 3/15/2018 0300

DEM Incident No:

No Further Action: ☒

Responsible Party: Plains Marketing

County: Mountrail

Twp Rng Sec Qtr: 156 91 27

Lat Long + Method: 48.30214 -102.37480 Interpolation from map

Location Description: 1/2 mile south of Stanley, Nd on Hwy 8

Submitted By Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 0.025 Miles

Type of Incident: truck hose leak

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude Oil

Volume of Release: 10 gallons

Duration of Release: 1 minutes

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Driver hose leak while unloading oil

Risk Evaluation:

None

Potential Env. Impacts:

Soil

Action Taken/Planned:

Absorbed oil and scraped up contaminated soil into a container

Wastes Disposal Location:

prairie disposal

Other Agencies Involved:

Updates

Date: 3/16/2018 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Notes:

Release, due to a truck hose leak, was not contained. An inspection is needed to determine if proper clean up was conducted.

Updated Volume: None at the time of this update

Date: 3/19/2018 **Status:** Inspection

Author: DeVries, Taylor

Notes:

Inspection Date: 3/19/2018

Arrived on location at 1520. There is a very light sheen in the puddles at the provided GPS coordinates. Due the minimal sheen, no further follow-up is needed at this time. Photos were taken and can be found in the report folder.

Updated Volume: None at the time of this update