General Environmental Incident Summary

Incident: 5859 DEM Incident No:	<i>Notice:</i> 9/19/2018	<i>Occurred:</i> 9/18/2018 1645 <i>No Further Action:</i> ✓
Responsible Party:	Precision Underground	No Further Action. 🗸
County:	Williams	
Twp Rng Sec Qtr:	156 99 4 NW	
Lat Long + Method:	48.28410 -103.42690	Navigation quality GPS
Location Description:	intersection of CR 8 and 127th Ave NW, Epping	
Submitted By Info:	Donald Billingsley	
	2712 E Rosser	
	Apt 9	
	Bismarck ND	
Received By Info:		
Contact Info:		
contact mic.	968 industrial DR	
	Bismarck ND 58504	
Affected Medium:	03 - soil	
Near. Occupied Bldg:	0.5 Miles	
Type of Incident:	HDD frac out	
Release Contained:	Yes	
Reported to NRC:	Unknown	
Contaminant:	Wyo-Ben Bentinite	
Volume of Release:	10 gallons	
Duration of Release:	5 minutes	
Agriculture Related:	No	
EPA Extremely		
Hazardous Substance:		
Number of Fatalities:	0	
Number of Injuries:	0	
Cause of Incident:		
ground is so dry the water went up through cracks in ground		
Risk Evaluation:		
None		
Potential Env. Impacts:		
none Action Taken/Planned:		
suck vac		
Wastes Disposal Location:		
on right of way		
Other Agencies Involve	ed:	

Updates

Date: 9/19/2018 Status: Reviewed - No Action Required

Author: Stockdill, Scott

Notes:

According to the responsible party, this incident didn't impact waters of the state and the substance is inert in nature. No follow-up is necessary.

Updated Volume: None at the time of this update